

MERRITT TENNIS & TRACK SYSTEMS

(405) 947-7918, FAX (405) 947-2635, 1-800-870-0722

EMAIL: paul@merrittcompanies.net

WEB PAGE: www.merritttennisandtrack.com

www.classicumpirechair.com,

www.tulsatenniscourts.com, Tulsa, OK. 918-856-3428

www.goalsetter.com, www.douglasindustries.com

www.plexipave.com, www.deco.com, www.sportsbuilders.org

P.O. Box 75728, OKC. Okla. 73147

917 N. Tulsa Ave., Oklahoma City, OK. 73107

I.A.A.F. CERTIFIED TRACK SURFACE, PLEXITRAC XL

CALIFORNIA PRODUCTS CORP. "PLEXIPAVE", PLEXITRAC DIST., APPLICATOR

DECO & DECO TURF APPLICATOR "THE SURFACE OF CHAMPIONS"

ADVANTAGE SURFACING PRODUCTS APPLICATOR

COURT HARDWARE & BASKETBALL GOALS

Robert B. Johnston, City Manager

Monday, June 12, 2023

City of Clinton, OK

415 Gary Freeway, PO Box 1177

Clinton, OK 73601

580-323-0261 office, 580-335-1551 cell, robert.johnston@clintonok.gov

1 –Joe Baker Park: Basketball Court Facility, repair & resurfacing, NEW GOALS NEEDED.



Mr. Weichel:

Per your request; following is our observation, recommendation, scope of work & price to complete the repair, resurfacing & upgrade of the existing 1 asphalt basketball court in your photos located at your Facility.

OBSERVATION:

Structurally, the court is normal for age. Site & court perimeter drainage is adequate. Generally; all courts have random cracking which is normal.

NO existing acrylic surface is attached to the sub-straight.

RECOMMENDATION:

Complete attached specification for application on asphalt surface's .

SCOPE OF WORK: COLOR SELECTED BY OWNER; Google Sportmaster colors, for options / selection

CITY TO APPLY HERBICIDE TWICE, 2 WEEKS PRIOR TO MERRITT'S ARRIVAL

REPAIR & RESURFACE 1 EXISTING ASPHALT COURT: 50' x 100'

http://www.plexipave.com/tech_docs/specs/10.18plexipavesystemasphaltsurfaces.pdf

HIGH PRESSURE, 3,500 PSI MIN., CLEAN & RINSE WITH PRESSURED WATER.

ALLOW DRYING

ROUT, GRIND OR SAW & FILL CONTROL JTS. & CRACKS W/ PLEXIPAVE CRACKFILLER,(

(Cracks will reappear in the future as hairline cracks due to expansion & contraction)

<http://www.plexipave.com/specifications/specs/10.10crackfiller.pdf>

GRIND AND PREP REPAIR AREAS ENTIRE SURFACE

ALLOW 24 HOUR MIN. CURE

MARK, PRIME & REPAIR LOW OR BIRDBATH AREAS WITH COURT PATCH BINDER.

<http://www.plexipave.com/specifications/specs/10.14courtpatchbinder.pdf>

APPLY 4175 ACRYLIC TACK COAT.

APPLY ONE COAT CEMENT SLURRY

ALLOW 24 HR CURE,



ACID TREAT & RINSE

APPLY ONE COAT ACRYLIC RESURFACER WITH SAND,

<http://www.plexipave.com/specifications/specs/10.8acrylicresurfacer.pdf>

APPLY 2 COAT FORTIFIED ACRYLIC COLOR, (COLOR BY OWNER).
<http://www.plexipave.com/specifications/specs/10.2fortifiedplexipave.pdf>
LAYOUT AND APPLY NEW TEXTURED PLAY LINES, 1 - BASKETBALL , LOGOS P.O.R.
<http://www.plexipave.com/specifications/specs/10.4hi-hideplexicolorlinepaint.pdf>
ONE YEAR GUARANTEE, (SEE ATTACHED), CRACK WILL REAPPERAR AS HAIRLINE CRACKS

TO COMPLETE THE SURFACING PROJECT WITH NO WEATHER / TEMPERATURE DELAYS WOULD REQUIRE: 6 TO 10 DAYS

TOTAL RESURFACING: 1 – 5,000 S.F. COURT @ \$ 3.65 / S.F. =	\$ 18,250.00	
A 2" ASPHALT OVERLAY & SURFAING WOULD BE:	\$ 45,333.30	
NEW GOALSETTER MVP GOALS INSTALLED:	\$ 8,598.00	

Sincerely;

Paul L. Merritt
President
Cell # 405-850-0720

All work will follow the attached specifications and product data sheets supplied by California Products Corp. , SPORTMASTER and the U.S.T.C. & T.B.A. & The American Sport Builders Assoc.

Certificates of insurance will be provided upon request.

Thank you for the opportunity to quote.

Sincerely,

Paul L. Merritt
President

MEMBER: UNITED STATES TENNIS COURT & TRACK BUILDERS ASSOC.

SEE OUR WEB SITE FOR REF. & SPEC. INFORMATION;
www.merritttennisandtrack.com

See Facebook: merritttennisandtrack.com

facebook



TULSA GATHERING PLACE COURT CONTRACTOR, COMING JUNE OF 2018

**GAME, SET
& MATCH**
FOR A BETTER
TOMORROW